

Washing Machine Motors

Motor Structure	Type		Number of phases	Frequency	Voltage	Output Power		Speed		Current		Ins. Cl.	IP	Rotation
	Com. Code	Mfg. Code				Low	High	Low	High	Low	High			
						W	W	R.P.M	R.P.M	A	A			
Permanent Split Phase (Capacitor Run)	WM850	17200	1	50	220/230	55	160	300	2800	1.3	3.1	B	00	C.W / C.C.W
	WM840	17160	1	50	220/230	55	125	300	2800	2.6	3	B	00	C.W / C.C.W